








SUBSTANCE	LITHIUM EP GREASES
IDENTIFICATION	Refined mineral oil, brown in colour.
PROCESS/OR USE	Grease, lubricator.
RISKS TO HEALTH	Extensive skin contact may result in skin disorders. High-pressure injection under skin.


CAN THE EXPOSURE BE ELIMINATED **NO** Details specified below








	<p>FIRST AID MEASURES</p> <p>EYES: Flush eyes with large amounts of water. If symptoms persist, seek medical help. SKIN: Wash with large quantities of water and remove contaminated clothing. INHALATION: Remove to fresh air and seek medical advice. INGESTION: Do not induce vomiting, wash mouth out with water and seek medical advice.</p>
---	--

COPY MUST BE SENT WITH INJURED PARTY TO HOSPITAL

	<p>FIRE FIGHTING MEASURES (Tick Box)</p> <p>  <input type="checkbox"/>  <input checked="" type="checkbox"/>  <input type="checkbox"/>  <input checked="" type="checkbox"/> </p>
--	---

	<p>SPILLAGE & ENVIRONMENTAL DETAILS</p> <p>Prevent entry into drains, sewers or watercourse. Scrape up and transfer to suitable containers with the use of absorbent material. Clean affected area well to prevent slippery surface.</p>
---	---

	<p>EXPOSURE LIMITS (EH 40)</p> <p>Time Exposed: _____ Number of People Exposed: _____</p> <p>Workplace Exposure Limit (WEL)</p> <p><i>Long Term Exposure Limit - 8 Hour TWA</i> - ppm - mg.m⁻³</p> <p><i>Short Term Exposure Limit - 15 Minute</i> - ppm - mg.m⁻³</p>
--	---

<p>PPE</p> <p>(Tick Box)</p>	<p>  <input checked="" type="checkbox"/>  <input checked="" type="checkbox"/>  <input type="checkbox"/>  <input type="checkbox"/>  <input type="checkbox"/>  <input type="checkbox"/>  <input checked="" type="checkbox"/> </p>
-------------------------------------	--

<p>CONTROL MEASURES</p>	<p>Store drums undercover and avoid sources of heat or ignition. To be stored in a bunded area and only store necessary quantities.</p> <p>Wear correct PPE.</p>	<p>Management</p> <p>Operatives</p>
--------------------------------	--	---

